



14th Floor, Centre Tower
3300 Bloor Street West
Toronto, Ontario
Canada M8X 2X4
Tel.: 416.734.3300
Fax: 416.231.1626
Toll Free: 1.877.682.8772

www.tssa.org

December 07, 2015

SUSAN TURNER
PARKER HANNIFIN INSTRUMENTATION GROUP CANADA
4635 DURHAM RD S
GRIMSBY ON L3M 4G4
CA

Service Request Type.: BPV-National BC
Service Request No.: 1729762
Your Reference No.: HB SERIES BALL VALVES - RENEW CRN 0C10356.5 - NAT'L SERV.
Registered to.: PARKER HANNIFIN - INSTRUMENTATION PRODUCTS DIVISION

Dear SUSAN TURNER,

Please find enclosed the original response from BC, registered under the CRN No.: 0C10356.51.

As all jurisdictional fees are handled by the Technical Standards and Safety Authority (TSSA), you do not pay any jurisdictions directly.

Should you have any questions or require further assistance, I will be happy to assist you.
For general enquiries, please contact a Customer Service Advisor at 1.877.682.TSSA (8772) or e-mail customerservices@tssa.org. When contacting TSSA regarding this file, please refer to the Service Request number provided above.

Yours truly,

Tanya Francis
Administrative Assistant_ BPV Engineering
Tel. : 416-734-3423
Fax : 416-231-6183
Email : tfrancis@tssa.org



505 - 6th Street, Suite 200
New Westminster, BC V3L 0E1

Toll Free: 1-866-566-SAFE
Fax: (778) 396 - 2064
www.safetyauthority.ca

TECHNICAL STANDARDS & SAFETY AUTHORITY
14TH FLOOR CENTRE TOWER-3300 BLOOR STREE
TORONTO ON M8X 2X4

Date: October 19, 2015
Account #: 35231
Journal #: 63763
Our File #: 5557240

Attn: TANYA FRANCIS

Re: Application for Design Registration

The design, as detailed in your, TSSA Service Request No. 1729762, for a Fitting is accepted for registration as follows:

Registered To: PARKER HANNIFIN INC. **CRN:** 0C10356.51

MAWT: 400 deg F

MAWP: 10000 psig

Drawing #: Catalog 4131-BV pgs 22 thru 27

Conditions Of Registration:

Registratoin of HB Series Ball Valves - Catalog 4121-BV (JULY 2014) pgs 22 through 27.

This design was registered based on a technical review performed by the province of initial registration in accordance with the Association of Chief Inspectors policy on reciprocal recognition of design review.

Reviewer's Notes:

As required by CSA B51 4.2.1, this registration expires on September 18, 2025. This CRN is valid until the expiry date as long as the Manufacturer maintains a valid quality control program verified by an acceptable third-party agency until that date. Should the certification of the quality control program lapse before the expiry date, this registration shall become void.

Contact me if you have any questions. The invoice for registration will be forwarded under separate cover.

SHARON PETERS

boiler.designregistration@safetyauthority.ca
Design Administration

cc: